



Specialty Conditioning Assessment for Boats

Specialty Services (Settlement Assistance) (800) 351-3133, menu option 3.

ABOVE AVERAGE	Far above average compared to vehicles of same year & type.
AVERAGE	Average or typical compared to vehicles of same year & type.
BELOW AVERAGE	Below average compared to vehicles of same year & type.

CURRENT YEAR - 2 MODEL YEARS

INTERIOR (consoles, seating, cabinets and interior trim)

1	Above Average	This is not used on newer vehicles as average denotes a vehicle in like new condition.
2	Average	Like new condition with no damage.
3	Below Average	Stains. 1-2 gauges broken. Tears/cuts/holes. Split/cracked.

EXTERIOR (hull, deck, mast, sails and rails)

1	Above Average	This is not used on newer vehicles as average denotes a vehicle in like new condition.
2	Average	Like new condition with no damage.
3	Below Average	Collision dents. Rust or oxidized paint. Sun/weather damage.

MECHANICAL (Engine, Drive, Power tilt, trim tabs)

1	Above Average	This is not used on newer vehicles as it denotes a rebuilt engine.
2	Average	Clean/good condition. Maintenance performed and documented.
3	Below Average	Belt/accessories show wear/corrosion. Oil/fluid leaks.

CANVAS/STORAGE COVERS

1	Above Average	This is not used on newer vehicles as average denotes a vehicle in like new condition.
2	Average	Like new condition with no damage.
3	Below Average	Stains. Tears/cuts/holes. Split/cracked.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
--	------------------------------------	---

3 MODEL YEARS OLD – 5 MODEL YEARS OLD INTERIOR

(consoles, seating, cabinets and interior trim)

1	Above Average	No damage/fading/discoloring. Soil removed with detail.
2	Average	Slight Wear. Small tears. Splits in seats/ or cracked
3	Below Average	Large tears/Splits/cracks 1-2 gauges broken. Seams separated.

EXTERIOR (hull, deck, mast, and rails)

1	Above Average	No damage of any type. Recent paint job. Shiny chrome.
2	Average	1-3 small dings on close inspection. Minor weather exposure.
3	Below Average	Large collision dents. Oxidized/extensive fading.

MECHANICAL (Engine, Drive, Power tilt, trim tabs)

1	Above Average	Documented recent rebuild or new engine replacement.
2	Average	Maintenance performed/documented. Clean/good condition. Minor oil/fluid leaks.
3	Below Average	Belt/accessories show wear/corrosion or need replacing. Major oil/fluid leaks.

CANVAS/STORAGE COVERS

1	Above Average	No damage/fading/discoloring. Soil removed with detail.
2	Average	Slight Wear. Small tears. 1-3 holes/burn marks.
3	Below Average	Large tears/burn holes. Seams separated.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
--	------------------------------------	---

PN 3158011-0713

Specialty Conditioning Assessment for Boats

ABOVE AVERAGE	Far above average compared to vehicles of same year & type.
AVERAGE	Average or typical compared to vehicles of same year & type.
BELOW AVERAGE	Below average compared to vehicles of same year & type.

6 MODEL YEARS OLD – 9 MODEL YEARS OLD INTERIOR

(consoles, seating, cabinets and interior trim)

1	Above Average	No damage/fading/dicoloring. Soil removed with detail.
2	Average	Slight Wear. Tears. Splits in seats/ or cracked.
3	Below Average	Large tears/burn holes. Several gauges broken. Seams separated. Seats missing or shredded.

EXTERIOR (hull, deck, mast, sails and rails)

1	Above Average	No damage of any type. Recent paint job. Shiny chrome.
2	Average	Multiple dings. Small collision dents. 1-2 scrapes in paint. 1-3 trim items broken.
3	Below Average	Large collision dents. Oxidized/extensive fading. Severe rust. Primer areas.

MECHANICAL (Engine, Drive, Power tilt, trim tabs)

1	Above Average	Documented recent rebuild or new engine replacement.
2	Average	Maintenance performed/documented. Minor oil/fluid leaks. Belts/accessories show wear/corrosion.
3	Below Average	Extensive oil/fluid leaks. Belt/accessories need replacing. Needs mechanical work. May not drive.

CANVAS/STORAGE COVERS

1	Above Average	No damage/fading/dicoloring. Soil removed with detail.
2	Average	Stains. Small tears. 1-3 holes/burn marks.
3	Below Average	Large tears/burn holes. Seams separated.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
---	---	--

10 MODEL YEARS OLD AND OLDER

INTERIOR (consoles, seating, cabinets and interior trim)

1	Above Average	No damage/fading/dicoloring. Soil removed with detail.
2	Average	Stains. Large tears. Numerous holes. Sagging in areas.
3	Below Average	Large tears. Several gauges broken. Seams separated. Seats missing or shredded.

EXTERIOR (hull, deck, mast, sails and rails)

1	Above Average	No damage of any type. Recent paint job. Shiny chrome.
2	Average	Multiple dings. Small collision dents. 1-2 scrapes in paint. 1-3 trim items broken. Poor re-paint.
3	Below Average	Large collision dents. Oxidized/extensive fading. Severe rust. Primer areas.

MECHANICAL (Engine, Drive, Power tilt, trim tabs)

1	Above Average	Documented recent rebuild or new engine replacement. Maintenance performed/documented.
2	Average	Minor oil/fluid leaks. Belt/accessories show wear/corrosion.
3	Below Average	Extensive oil/fluid leaks. Belt/accessories need replacing. Needs mechanical work. May not drive.

CANVAS/STORAGE COVERS

1	Above Average	No damage/fading/dicoloring. Soil removed with detail.
2	Average	Stains. Small tears. Numerous holes. Sagging in areas.
3	Below Average	Large tears/burn holes. Seams separated. Canvas/Cover missing or shredded.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
---	---	--

