

SOLERA Specialty Conditioning Assessment for Golf Carts

Specialty Services (Settlement Assistance) (800) 351-3133, menu option 3.

ABOVE AVERAGE	Far above average compared to vehicles of same year & type.
AVERAGE	Average or typical compared to vehicles of same year & type.
BELOW AVERAGE	Below average compared to vehicles of same year & type.

CURRENT YEAR - 2 MODEL YEARS

Appearance (Fiberglass Roof/Windshield, Seat, Fiberglass Body, Wheels, Accessories)

1	Above Average	This is not used on newer vehicles as average denotes a vehicle in like new condition. With the exception of Custom/upgraded.
2	Average	Like new condition with no damage.
3	Below Average	Large cracks in body. Severe scratches on windshield. Missing or damaged equipment. Torn seat/multiple burn marks.

MECHANICAL (BATTERIES, ENGINE, DRIVE; if inaccessible assume typical, required proof maintenance or rebuild)

1	Above Average	This is not used on newer vehicles as it denotes a rebuilt engine or new batteries.
2	Average	Clean/good condition. Maintenance performed and documented.
3	Below Average	Improperly functioning equipment. Needs Maintenance.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
--	------------------------------------	---

3 MODEL YEARS OLD – 5 MODEL YEARS OLD

Appearance (Fiberglass Roof/Windshield, Seat, Fiberglass Body, Wheels, Accessories)

1	Above Average	No damage/fading/discoloring/cracking. No tears/burn marks.
2	Average	Slight Wear. Small scuffs. Some imperfections. No tears/minor burn mark.
3	Below Average	Large cracks in body. Severe scratches on windshield. Missing or damaged equipment. Torn seat/multiple burn marks.

MECHANICAL (BATTERIES, ENGINE, DRIVE; if inaccessible assume typical, required proof maintenance or rebuild)

1	Above Average	Documented recent rebuild, new engine replacement, or new batteries. Custom/Upgrade.
2	Average	Maintenance performed/documented. Clean/good condition.
3	Below Average	Engine/batteries need replacing. Lack of maintenance.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
--	------------------------------------	---

6 MODEL YEARS OLD – 9 MODEL YEARS OLD

Appearance (Fiberglass Roof/Windshield, Seat, Fiberglass Body, Wheels, Accessories)

1	Above Average	No damage/fading/discoloring/cracking. No tears/burn marks.
2	Average	Slight Wear. Small scuffs. Some imperfections. No tears/1-2 small burn marks.
3	Below Average	Large cracks in body. Severe scratches on windshield. Missing or damaged equipment. Torn seat/multiple burn marks.

MECHANICAL (BATTERIES, ENGINE, DRIVE; if inaccessible assume typical, required proof maintenance or rebuild)

1	Above Average	Documented recent rebuild, new engine replacement, or new batteries. Custom/modified.
2	Average	Maintenance performed/documented. Clean/good condition.
3	Below Average	Engine/batteries need replacing. Needs mechanical work.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
--	------------------------------------	---

PN 3158016

Specialty Conditioning Assessment for Golf Carts

ABOVE AVERAGE	Far above average compared to vehicles of same year & type.
AVERAGE	Average or typical compared to vehicles of same year & type.
BELOW AVERAGE	Below average compared to vehicles of same year & type.

10 MODEL YEARS OLD AND OLDER.

Appearance (Fiberglass Roof/Windshield, Seat, Fiberglass Body, Wheels, Accessories)

1	Above Average	No damage/fading/dicoloring/cracking. No tears/burn marks.
2	Average	Small tears/1-2 small burn marks in seat. Small scuffs/minor cracks to body. Paint discolored. Minor scratches on windshield.
3	Below Average	Large cracks in body. Severe scratches on windshield. Missing or damaged equipment. Torn seat/multiple burn marks.

MECHANICAL (BATTERIES, ENGINE, DRIVE; if inaccessible assume typical, required proof maintenance or rebuild)

1	Above Average	Documented recent rebuild, new engine replacement, or new batteries. Maintenance performed/documented.
2	Average	Maintenance performed/documented. Clean/good condition.
3	Below Average	Engine/batteries need replacing. Needs mechanical work.

TIRES

Above Average New/over 80% of tread remains	Average 30-79% of tread remains	Below Average 0-29% of tread remains
--	------------------------------------	---



© 2023 Audatex North America, Inc.